



Technical Bulletin

178 Blackstone Avenue Jamestown NY 14701

www.jamestown.com

716.665.5313

Date: *July 11, 2011* No.: 007
To: Customer Service, Engineering, Estimating, Operations, Sales, Valued JMP Dealers
Subject: *M01-J Velocity Alarms and M02 Vapor Alarms - Service Only*

The original standard Jamestown Velocity Alarm (M01-J) and the standard Jamestown Vapor Detector (M02) will no longer be available for new fume hoods as of the issue date of this Technical Bulletin.

Both of the alarms are slightly wider (4 1/8") than the width of the new Gen5 Fascia posts (3 1/2") and therefore, do not fit within the confines of the overall width of the hood. In addition, most specifications are written around specific manufacturers alarms (Tel, Alnor, etc.). This, in turn, renders the design criteria of the Jamestown Velocity Alarm obsolete.

Note: This bulletin applies to the following catalog codes: M01-J, M01-J-L, M02, M02-L (JMP Internal Part #'s 02900400, 02900401)

Contact JMP for more information.

Fume Hood Engineering
Jamestown Metal Products, LLC