



# SEFA 8.0 CABINET SURFACE FINISH TESTS

Performed for: **Jamestown Metal Products**  
178 Blackstone Avenue  
Jamestown, NY 14701

Item Tested  Metal Panel

Reference: Scientific Equipment & Furniture Association (SEFA)  
Laboratory Furniture Casework, Shelving and Tables Recommended Practices  
SEFA 8 M-1999

## Section 8.0 Cabinet Surface Finish Tests

### Results:

8.1 Chemical Spot Test  
See detailed results on attached form.

Four Level 3 conditions permitted. Rating:  Pass  Fail

There are four (4) Level 3 conditions evident

8.2 Hot Water Test Rating:  Pass  Fail

There are no visible effects from the hot water

8.3 Impact Test Rating:  Pass  Fail

There are no checks or cracks due to impact

8.4 Paint Adhesion on Steel Rating  Pass  Fail

90% or more of the squares did show an intact finish after being brushed lightly with a soft brush

8.5 Paint Hardness on Steel  
Note: Test preformed utilizing Paul N. Gardner Model 3363 Pencil Scratch Hardness Test, Meets ASTM D3363. Minimum acceptance level: 4H Hardness  
Rating:  Pass  Fail

The finish withstood the abrasion of a 4H pencil without penetration

Tests performed by:  Neil M. Ball  Title:  Environmental Analyst


Neil M. Ball  
Signature

5-8-09  
Date

State of Wisconsin  
County of Sheboygan

This document was signed before me on 5/8/09

Jennifer Beemel  
Jennifer Beemel - Notary Expires 4-21-2013



**CARDINAL ENVIRONMENTAL**  
3303 Paine Avenue  
Sheboygan, WI 53081  
(920)459-2500 \* (800)413-7225  
Fax (920)459-2503  
www.cardinalenvironmental.com